


STORAGE ROOM(unfinished) REMODELED into – MAN CAVE

BEFORE

- Drywall walls and knock-down ceiling added.
- HVAC & electrical repair.
- Red/black/gray marble epoxy over concrete flooring.
- Cabinets install and stainless steel tile backsplash.



AFTER



STORAGE ROOM(unfinished) – REMODELED into – MAN CAVE

BEFORE

- Custom wood shelf and window molding.
- Gray woven roller shades.
- Chandelier, recessed, and undercabinet light fixtures.



AFTER



STORAGE ROOM(unfinished) – REMODELED into – MAN CAVE

BEFORE

- Custom wood floor and door trim.
- Semi-gloss gray paint.
- Sump pump pipe moved to fit under cabinets.



AFTER



FIREPLACE REMODEL

BEFORE

Wood burning brick fireplace removed.



AFTER

New Gas Fireplace insert, custom alder wood cabinets/mantle, television/ceiling speakers, recessed lights and flagstone surround.



KITCHEN REMODEL

BEFORE



AFTER



- Demo of counter tops, backsplash and wall surround on kitchen island.
- Downdraft install for new oven.
- Electrical fixes.

KITCHEN REMODEL

BEFORE



AFTER



- Custom granite countertops.
- Custom cabinets on backside of kitchen island.
- Stone tile on kitchen island.

KITCHEN REMODEL

BEFORE



- New stainless steel Kitchen Aid fridge, dishwasher, and oven.
- New stainless steel farm-style sink and touchless faucet.
- Custom travertine and clay/glass back splash.
- New satin nickel knobs and handles.

AFTER




BEDROOM REMODEL

BEFORE



- HVAC added into new soffit.
- New carpet, paint, curtains, and light fixtures.

AFTER



OFFICE REMODEL

BEFORE



- New hardwood flooring, paint, and roller shades.
- New desk, chair, and artwork.
- Closet remodel with custom cabinets.

AFTER



BASEMENT CEILING REMODEL

BEFORE



AFTER



- Entire basement popcorn ceiling torn down.
- New ceiling installed with knockdown texture.
- Wall drywall repair and all walls painted with new primer paint.
- HVAC, electrical, and lighting repair.